

Arborist to monitor road removal and channel modifications.
 Most tree's root zones are restricted by the existing channel.
 Excavations for pools should favor the east side of the channel to avoid trees' root zones. The riparian restoration plan allows for field fitting around trees' root zone.

- Trees with blue root zones must be retained to maintain integrity of riparian area.
- Retention of trees requires planning to avoid excavations into critical root zones
- Spread 10cm of wood mulch throughout root zones
- Arborist supervision required during road grading and excavations for building foundations.

The arborist must supervise all excavations for retaining walls at boundary of critical root zones of Trees 2360, 2475, 2445.

Blind forms and minimal overexcavation required when building Unit 2. Retaining structure must be designed to accommodate root zone. See notes in tree inventory table.

Trees with blue critical root zones must be retained to maintain integrity of riparian area.

Stairs and road will affect District trees not shown on this plan or assessed in this arborist report.

LEGEND

- TREE PROTECTION ZONE
- AREA OF CONFLICT
- TREE PROTECTION FENCE
- SURVEYED TREE TO BE RETAINED
- UN-SURVEYED TREE TO BE RETAINED
- TREE TO BE REMOVED

REFERENCE DRAWINGS

1. Base Survey by: Chapman surveying
2. A 1 00 OVERALL SITE PLAN NOV 10 22
3. MS2868-19046-T04

NOTES

1. The location of un-surveyed trees on this plan is approximate. Their location and ownership cannot be confirmed without being surveyed by a Registered BC Land Surveyor.
2. All tree protection fencing must be built to the relevant municipal bylaw specifications. The dimensions shown are from the outer edge of the stem of the tree.
3. The tree protection zone shown is a graphical representation of the critical root zone, measured from the outer edge of the stem of the tree. (½ the trees diameter was added to the graphical tree protection circles to accommodate the survey point being in the center of the tree)
4. Any construction activities or grade changes within the Root Protection Zone must be approved by the project arborist.
5. This plan is based on a topographic and tree location survey provided by the owners' Registered British Columbia Land Surveyor (BCLS) and layout drawings provide by the owners' Engineer (P Eng).
6. This plan is provided for context only, and is not certified as to the accuracy of the location of features or dimensions that are shown on this plan. Please refer to the original survey plan and engineering plans.



3559 COMMERCIAL STREET
 VANCOUVER BC | V5N 4E8
 T 604.733.4886

Drawing title: Tree Management Plan
 Project address: Daffodil Drive
 Client: Aquila

Drawing No: 5
 Date: 2023/03/22
 Drawn by: MH
 Page Size: TABLOID 11"x17"

Page #
 1 of 1

Arboricultural Inventory and Report

For:
Aquila

Site Location:
Daffodil Drive

DISTRICT LOT 1374 PARCEL C REFERENCE PLAN 3355
EXCEPT REFERENCE PLAN 11716
PID 010-068-775
(No street address)
West Vancouver, BC

Submitted to:
Jamie Harper


Date: September 16, 2021
Updated: February 28, 2023
March 22, 2023



The following Diamond Head Consulting staff conducted the on-site tree inventory and prepared or reviewed the report.

All general and professional liability insurance and staff accreditations are provided below for reference.

Supervisor:



Michael Harry, B.Sc., MSFM
Registered Professional Forester
ISA Certified Arborist (PN-8025A)
ISA Tree Risk Assessment Qualified (TRAQ)
BC Wildlife and Danger Tree Assessor (P2528)
Biologist in Training

Project Staff:



Mitch Davis, Dip. Forest and Natural Areas Management
ISA Certified Arborist (PN-9077 A)
ISA Tree Risk Assessment Qualified (TRAQ)

Senior Review:



Mike Coulthard, R.P.Bio., R.P.F.
Senior Forester, Biologist
ISA Tree Risk Assessment Qualified (46)
BC Wildlife and Danger Tree Assessor

Please contact us if there are any questions or concerns about the contents of this report.

Contact Information:

Phone: 604-733-4886
Email: mikeharry@diamondheadconsulting.com
Web site: www.diamondheadconsulting.com

Insurance Information:

WCB: # 657906 AQ (003)
General Liability: Northbridge General Insurance Corporation - Policy #CBC1935506, \$10,000,000
Errors and Omissions: Lloyds Underwriters – Policy #1010615D, \$1,000,000

Scope of Assignment:

Diamond Head Consulting Ltd. (DHC) was retained to complete an arboricultural assessment to supplement the proposed development application. This report contains an inventory of protected on and off-site trees and summarizes management recommendations with respect to future development plans and construction activities. Off-site trees are included because pursuant to municipal by-laws, site owners must include the management of off-site trees that are within the scope of the development. This report is produced with the following primary limitations, detailed limitations specified in Appendix 7:

- 1) Our investigation is based solely on visual inspection of the trees during our last site visit. This inspection is conducted from ground level. We do not conduct aerial inspections, soil tests or below grade root examinations to assess the condition of tree root systems unless specifically contracted to do so.
- 2) Unless otherwise stated, tree risk assessments in this report are limited to trees with a *high* or *extreme* risk rating in their current condition, and in context of their surrounding land use at the time of assessment.
- 3) The scope of work is primarily determined by site boundaries and local tree-related bylaws. Only trees specified in the scope of work were assessed.
- 4) Beyond six months from the date of this report, the client must contact DHC to confirm its validity because site base plans and tree conditions may change beyond the original report's scope. Additional site visits and report revisions may be required after this point to ensure report accuracy for the municipality's development permit application process. Site visits and reporting required after the first submission are not included within the original proposal fee and will be charged to the client at an additional cost.

The client is responsible for:

- Reviewing this report to understand and implement all tree **risk**, removal and protection requirements related to the project.
- Understanding that we did not assess trees off the subject property and therefore cannot be held liable for actions you or your contractors may undertake in developing this property which may affect the trees on neighboring properties.
- Obtaining a tree removal permit from the relevant municipal authority prior to any tree cutting.
- Obtaining relevant permission from adjacent property owners before removing off-site trees and vegetation.
- Obtaining a timber mark if logs are being transported offsite.
- Ensuring the project is compliant with the tree permit conditions.
- Constructing and maintaining tree protection fencing.
- Ensuring an arborist is present onsite to supervise any works in or near tree protection zones.

Table of Contents

1.0	Introduction	1
1.1	Site Overview	1
1.2	Proposed Land Use Changes	2
1.3	Report Objective.....	2
2.0	Process and Methods	4
2.1	Tree Inventory	4
2.2	Tree Risk Assessment.....	4
2.3	Tree Protection.....	4
3.0	Findings and Discussion.....	5
3.1	Windthrow risk assessment	7
3.2	Tree Risk Assessment.....	7
4.0	Tree Replacement	8
5.0	Summary and Next Steps	8
6.0	Tree Protection During Construction.....	10
Appendix 1	Complete Tree Inventory Table.....	10
Appendix 2	Site Photographs.....	39
Appendix 3	Tree Health and Structure Rating Criteria	43
Appendix 4	Tree Retention Value Rating Criteria.....	44
Appendix 5	Risk Rating Matrices.....	45
Appendix 6	Construction Guidelines.....	46
Appendix 7	Report Assumptions and Limiting Conditions	50

List of Figures

Figure 1.	The Daffodil Drive project site in context of the surrounding landscape and infrastructure.	3
-----------	--	---

List of Tables

Table 1:	Summary of the tree inventory from Daffodil Drive	6
----------	---	---

List of Photographs

Photo 1.	Overhead view of the subject area’s canopy.	39
Photo 2.	Overhead view of the southwest corner of the site at Daffodil Drive	39
Photo 3.	The middle of the site	40
Photo 4.	Typical crowns of conifers within the site.....	40
Photo 5.	The existing asphalt road / easement at the top of the site	41
Photo 6.	The riparian setback for the tributary.....	41
Photo 7.	Looking south down the existing gravel driveway.....	42

1.0 Introduction

1.1 Site Overview

The subject site is a large, forested lot near Eagle Harbour in the city of West Vancouver. It is accessed from Daffodil Drive to the south, and from Westport road to the east. Two watercourses flow through the site before converging together on Daffodil Drive. Eagle Creek flows along the southern property line, and a ditch runs along the north and east property lines. Both watercourses require that a 10m riparian setback be protected. Most of site has moderate slope and a southern aspect. The western most 15-20m of the site is flat and is where a driveway exists. A small wetland has developed on the uphill side of this road.

There are two forest types on site including a dense, mature coniferous forest, and a young, open deciduous forest. The larger by area is the mature conifer stand which consist of Douglas fir (*Pseudotsuga menziesii*), western redcedar (*Thuja plicata*), western hemlock (*Tsuga heterophylla*), with scattered bigleaf maple (*Acer macrophyllum*). The mature conifers likely originated following logging of the area 80-100 years ago. They form a homogenous stand with a dense canopy. Except for a few very large Douglas fir trees that stand taller than the surrounding stand, most of the trees within this stand have not adapted to stand alone and rely on the shelter provided by adjacent trees for stability. Soils in this stand are rocky, dry, and relatively thin.

Some of the trees have been topped in the past, resulting in the growth of large multi-stem tops. These old topping injuries are usually at about 10m above the ground, and the trees may have grown up to 35m. These may pose a risk to future development and infrastructure. Evaluating the risk posed by topped trees will require aerial assessments by a climber.

A second, distinct stand type is found on the flat western portion of the property. This stand has an open canopy with smaller trees. Species include a mix of pioneer deciduous and native conifers. Red alder (*Alnus rubra*) is the most common species, with scattered western redcedar and western hemlock trees. Soils are wet in this area which along with recent disturbance has influenced the trees that are growing here. The low-density structure of this stand has produced several nice, open grown cedars with good retention potential. Many of the red alder in this stand are generally healthy, but are not suitable for retention adjacent to a development because of the shallow rooting caused by a high water table resulting in a high windthrow risk.

[Follow this link or go to https://www.youtube.com/watch?v=f32Di6vAqAo to watch a short drone flyover of the site.](https://www.youtube.com/watch?v=f32Di6vAqAo)

1.2 Proposed Land Use Changes

The proposed development consists of subdividing the property into 36 residential units. The riparian area of Eagle Creek will be dedicated as park land, and the riparian area on the tributary will be protected under a covenant. Some habitat compensation and improvement works are planned for the tributary. In preparing this report, we reviewed the following information:

- Overall site plan, Aquilla, Oct 31, 2022
- Topographic and tree survey. Chapman Land Surveying Ltd, Oct 27, 2022

1.3 Report Objective

This report has been prepared to ensure the proposed development is compliant with the West Vancouver Interim Tree Bylaw No. 4892, 2016. Refer to Bylaw No 4892 for the complete definition of protected trees, summarized below as:

- a) Any tree greater than 75 cm DBH, or in the case of a tree with multiple stems, a combined stem DBH of 75 cm or more;
- b) Any replacement tree;
- c) Any retained tree; d) Any heritage tree;
- d) Any tree located within a Watercourse Protection Area or Foreshore Protection Area;
- e) Any tree of the following species, greater than 20 cm DBH: i. Arbutus (*Arbutus menziesii*); ii. Garry Oak (*Quercus garryana*); iii. Pacific yew (*Taxus brevifolia*); iv. Pacific dogwood (*Cornus nuttallii*); v. Yellow cedar (*Cupressus nootkatensis*); vi. Shore pine (*Pinus contorta var contorta*) that lie within the protected shoreline area as defined using the Provincial ecosystem zone mapping;
- f) Any tree that contains an active nest of any bird, or the nest, whether active or not, of an eagle, peregrine falcon, gyrfalcon, heron, osprey, or burrowing owl;
- g) Any tree that constitutes the habitat of a protected wildlife species under the Provincial Wildlife Act or Federal Migratory Bird Act.

This report outlines the existing condition of protected trees on and adjacent to the property, summarizes the proposed tree retention and removal, and suggests guidelines for protecting retained trees during the construction process.




Figure 1. The Daffodil Drive project site in context of the surrounding landscape and infrastructure.

2.0 Process and Methods

Michael Harry and Mitch Davis of DHC visited the site in April 2021. The following methods and standards are used throughout this report.

2.1 Tree Inventory

Trees on site and trees shared with adjacent properties were marked with a numbered tag and assessed for attributes including: species; height measured to the nearest meter; and, diameter at breast height (DBH) measured to the nearest centimeter at 1.4 m above grade. Off-site trees were inventoried, but not tagged. The general health and structural integrity of each tree was assessed visually and assigned to one of five categories: *excellent; good; moderate; poor; or dying/dead*. Descriptions of the health and structure rating criteria are given in 0.

Tree retention value, categorized as *high, medium, low, or nil*, was assigned to each tree or group of trees based on their health and structure rating, and potential longevity in a developed environment. Descriptions of the retention value ratings are given in 0. Recommendations for tree retention or removal were determined by taking in to account a tree's retention value rating, its location in relation to proposed building envelopes and development infrastructure.

2.2 Tree Risk Assessment

Tree risk assessments were completed following methods of the ISA Tree Risk Assessment Manual¹ published in 2013 by the International Society of Arboriculture, which is the current industry standard for assessing tree risk. This methodology assigns risk based on the likelihood of failure, the likelihood of impact and the severity of consequence if a failure occurs. Only on-site hazard trees that had *high* or *extreme* risk ratings in their current condition and in context of their surrounding land use were identified and reported in section 3.2. Appendix 5 gives the likelihood and risk rating matrices used to categorize tree risk. DHC recommends that on-site trees be re-assessed for risk after the site conditions change (e.g. after damaging weather events, site disturbance from construction, creation of new targets during construction or in the final developed landscape).

2.3 Tree Protection

Tree protection zones were calculated for each tree according to a 10 x DBH radius but may be modified based on professional judgement of the project arborist to accommodate species specific tolerances and site specific growing conditions.

¹ Dunster, J.A., Smiley, E.T., Matheny, N. and Lilly, S. (2013). Tree Risk Assessment Manual. *International Society of Arboriculture*. Champaign, Illinois.

3.0 Findings and Discussion

The tree inventory is summarized in Table 1. A complete tree inventory is provided in 6.0.

Trees On-site

There were 163 trees inventoried on the site. 79 of these trees are greater than 75cm DBH and considered protected under the Interim Tree Bylaw. 94 are between 10 and 74cm DBH and are protected as they are growing within the riparian setback areas. More than half of the trees (104) inventoried were given a 'moderate' retention value rating, meaning that they have potential to be retained but would need to be retained within groups or require treatments to make them stable. 28 are rated as high value, meaning that they have the characteristics required to be retained as individuals or at a stand edge. These high value trees require few treatments and bringing good amenity value to the project.

Tree retention opportunities on this site are limited by the grading and road works required for the development. Most trees within the core of the site require a stable group to be retained successfully. Retaining such a group is not feasible considering the site plan and required grading.

A group of red alder within the habitat compensation area in the southwest of the site is recommended for removal. These trees are not adapted to exposure, and the anticipated changes to hydrology is expected to cause the trees to decline and die. Removing and replacing the trees will create a more stable forest edge in the long term. It will also facilitate the creation of the proposed wetland habitat.

Root zones have been prescribed based on the species and tree conditions to ensure they will remain healthy and stable. Minor root zone conflict with the proposed building envelopes is expected, but can be managed to an acceptable level with proper planning and site supervision.

Successful retention of the significant edge trees will require:

- Maintenance of grades within the root zone, only building up with clear gravel when required
- Arborist supervision during foundation excavation to prune roots as required
- Planning of foundation excavation and landscape design to minimize required over excavation
- Installation of an automatic irrigation system to help compensate for any root loss.

Trees on Adjacent Properties

Few offsite trees have root zones that extend into the subject property. There were 7 privately owned off-site trees with tree protection zones extending into the subject site. Three trees growing on City property are within the zone of influence of the project. The connection to Daffodil Drive will require removal of a hemlock hedge (inventoried as two trees to mark each end) growing on City property. Offsite tree 567, a large cedar, is at the margin of the proposed road works but can be retained with the prescribed tree protection barriers.

The site entrance off Westport Road, and a proposed staircase and trail connection is included on the landscape plan. These features will likely affect trees that were not inventoried or assessed as part of this plan. The District-owned parcel off Westport was not included in this assessment.

Table 1: Summary of the tree inventory from Daffodil Drive containing the number of trees categorized by retention value and the recommended number to be retained or removed. The complete tree inventory is provided in 6.0.

*Note that City tree count does not include an assessment of trees affected by the proposed staircase off Westport Road.

Tree Species	Retention Value				Recommendation			
	High	Medium	Low	Nil	Remove	Retain	Wildlife	Total
On-site and shared trees								
Big-Leaf Maple		5	4	3	8	4		12
Bitter Cherry		1				1		1
Cascara		2	1		1	2		3
Douglas-Fir	12	15	2	1	15	15		30
Red Alder		21	14		10	20	5	35
Western Hemlock		6	1	1	5	3		8
Western Red Cedar	14	50	12	1	34	42	1	77
On-site totals	26	100	34	6	73	87	6	166
Off-site trees								
Big-Leaf Maple			1			1		1
Douglas-Fir			1			1		1
Paper Birch			1			1		1
Red Alder		1		1		2		2
Western Red Cedar	3					3		3
Off-site totals	3	1	3	1		8		8
City trees*								
Western Hemlock		2			2			2
Western Red Cedar		1			1			1
City totals		3			3			3
GRAND TOTAL					76	79	22	177

3.1 Windthrow risk assessment

Creating new forest edges and exposing trees to increased wind forces can result in windthrow, the failure of trees and forests during strong winds. We have identified the best available forest edges within 30m of the riparian areas to maintain the integrity of the forest within the protected riparian areas, and to minimize the risk of tree failures striking the proposed development. Trees that we recommended for retention are highlighted in blue on the Tree Management Plan. Loss of the recommended edge trees may have a cascading effect as weak trees that are unsuitable for retention are exposed, necessitating additional removals to minimize the risk of catastrophic stand failure.

The overall risk of windthrow on this site is moderate. In the mature conifer stand that covers most of the site, the stand has grown in a relatively dense, uniform structure. Most trees within this stand are not suitable for exposure. Dominant Douglas-fir and cedars that are taller than the surrounding stand and are well adapted to oncoming winds are the most stable trees. These dominant trees are typically larger than 75cm; the tree bylaw is a fair proxy for their identification.

The best available edges around Eagle creek in the south of the property consists of a solid row of conifers that have benefited from greater moisture availability and more growing room. This row protects a group of relatively weak red alder found along the banks of the watercourse. If the identified trees are adequately protected, the likelihood of windthrow around Eagle Creek is low.

The tributary in the northeast of the property has a greater likelihood of windthrow due to greater stem density, weaker trees, and poor rooting in coarse rocky ground. This forest edge will experience the greatest increase in wind forces following land clearing as it will be perpendicular to southern storm winds and be exposed at the top edge of the slope above the development. We have identified the best available forest edge, which is outside the 10m riparian setback.

Around the wetland and ditch found in the west of the site, the risk of windthrow is not expected to change because of the development or tree removals to accommodate restoration efforts. This stand is relatively short and there are large openings between trees; the trees are somewhat stable and adapted to withstand oncoming winds. Saturated soils reduce the rooting strength of the stand. There is no practical forest edge outside of the protected riparian area.

3.2 Tree Risk Assessment

There were no trees on this site that posed a *high* or *extreme* risk at the time of assessment. This is mainly because there are currently no structures or targets within striking range of most trees. The proposed development will create new forest edges and introduce new targets close to these trees. Recommendations have been made to reduce the risk of failure of retained trees. We recommend that the forest edges be reassessed for risk following land clearing.

4.0 Tree Replacement

The District of West Vancouver Tree Bylaw enables the requirement that replacement trees be planted for trees that are removed. The District will decide the quantity of replacement trees required and the project arborist or landscape architect can then prepare a tree replacement plan showing the location and species. Note that the concurrent Wildfire Hazard Assessment and DP permit guidelines require that no coniferous species be planted within 10m of a structure.

5.0 Summary and Next Steps

This Arboricultural Inventory Report outlines the existing condition of protected trees on and next to the proposed development, summarizes the proposed tree retention and removal, and suggests guidelines for protecting retained trees during the construction process. The owner is responsible for understanding and implementing all tree risk, removal and protection requirements related to the project and detailed in this report.

The supplied landscape plan includes several features that are offsite, including a staircase and grading from Westport Road. The proposed staircase and grading is offsite and not included in the scope of this assessment, but expect that it will affect a number of offsite trees.

Retention of trees and understory vegetation within the developable area is unlikely. The majority of the forest on the site <75cm DBH and therefore not protected under the bylaw.

Careful planning and arborist supervision during excavations for building foundations is required to protect retained trees 2358, 2360, 2475, 2445; and for road construction adjacent to trees 7676, 7277b, 7276, 7281, and 2473. Construction will require vertical excavations to avoid encroachment into the critical root zones. Blind forming and shotcrete retaining may be required. Arborist supervision is required during road grading. We recommend that the root zones of trees in this area be enhanced with 10cm of wood mulch and irrigation. The root zone enhancements will help the trees recover and adapt to new exposure.

We recommend that trees retained after the initial clearing be reassessed for risk by a qualified arborist, and that the land clearing activities be supervised by the project arborist. The project arborist can work to identify additional smaller trees that may be suitable for retention outside of the building envelopes and grading areas.

The project developer must also:

- Obtain a tree removal permit from the relevant municipal authority before any tree cutting.
- Get permission from adjacent property owners before removing off-site trees and vegetation on their respective properties.
- Obtain a timber mark if logs are being transported off site.
- Ensure the project is compliant with the tree permit conditions.
- Construct and maintain tree protection fencing.
- Have an arborist on site to supervise any works in or near tree protection zones.

Diamond Head did not assess trees growing outside of the subject property, including a District-owned lot on Westport Road. We, therefore, cannot be held liable for you or your contractors' actions developing this property that may affect trees on neighboring properties. Diamond Head recommends that on-site trees be re-assessed for risk after the site conditions change (e.g., after damaging weather events, site disturbance from construction, creation of new targets during construction or in the final developed landscape).

6.0 Tree Protection During Construction

The following tree protection measures should be considered during the construction process. Additional measures are provided in Appendix 6.

- A permanent tree protection zone should be established at the dimensions shown in Appendix 1. A tree protection fence should be established out from the base of all trees. Within these tree protection zones, no work activities or disturbance is permitted;
- Excavation that takes place within 2 meters of the base of any trees to be protected should be done carefully to ensure that roots are not ripped back toward the trees. A certified arborist should be on site to monitor the excavation if work is to be taken place within this zone. As soon as roots that are greater than 5cm in diameter are encountered, the remaining areas around the roots should be excavated with hand tools and the roots pruned off clean;
- Excavation and construction activities adjacent to protected trees can influence the moisture availability to their roots. Soil moisture conditions within the tree protection zones should be monitored during hot and dry weather. When soil moisture conditions are dry, supplemental irrigation should be provided; and
- If there are concerns regarding the clearance required for machinery and workers within the tree protection zone or just outside it, the project arborist should be consulted so that a pruning prescription can be developed or a zone surrounding the crowns can be established. All heavy machinery working adjacent to the trees (excavators, cranes, dump trucks, etc.) operating machinery within five meters of the crowns of these trees should be made aware of the proximity of these trees to their activities. If there is to be a sustained period of machinery working within five meters of the crowns of these trees a line with coloured flags should be suspended at the height of the crowns along the length of the protected trees.

Appendix 1 Complete Tree Inventory Table

The complete tree inventory below contains information on tree attributes and recommendations for removal or retention. Tree ownership in this inventory table is not definitive, its determination here is based on information available from the legal site survey, GPS locations, and field assessment during site visits. Tree Protection Zones are measured from the outer edge of a tree's stem. If using these measurements for mapping the tree protection zone, $\frac{1}{2}$ the tree's diameter must be added to the distance to accommodate a survey point at the tree's center. Where tree protection fencing is proposed to vary from the minimum municipal TPZ, comments will be included in the Retention/TPZ comments and shown on the Tree Management Plan. The TPZ is the tree protection zone size required by the relevant municipal bylaw or, if not defined, the project arborist.

Note that tree in this table include those significant trees > 75cm, and trees >15cm which are located within a riparian setback area.

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	311	On Site	Western Red Cedar	<i>Thuja plicata</i>	152	30	Good	Growing at toe of slope. Two stems union at 2m. Good attachment. Dominant tree in stand.	High	Remove	In conflict with proposed buildings and grading for walls.	9.1
Surveyed	312	On Site	Big-Leaf Maple	<i>Acer macrophyllum</i>	124	25	Poor	Heavily decayed base. Kretzschmaria at base. Stem overgrown with ivy.	Nil	Remove	In conflict with proposed building.	7.4
Surveyed	332	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	103	30	Good	Growing at toe of slope. Existing edge tree. Single straight stem. Codominant tree in stand.	High	Retain	This tree can be retained, but it is vulnerable to exposure following removal of 2358. Maintain grades within critical root zone.	6.2
Surveyed	333	On Site	Western Red Cedar	<i>Thuja plicata</i>	123	30	Good	Growing at toe of slope. Existing edge tree. Single straight stem. Dominant tree in stand. A great candidate for retention. Within protected riparian area	High	Retain	Design team to confirm finished grading around perimeter of building 19 will accommodate the critical root zone. The proposed building and grading for landscaping will likely push into the critical root zone of this tree. Arborist supervision is essential during excavations for building foundation, retaining walls, and landscaping.	9.8

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	334	On Site	Western Red Cedar	<i>Thuja plicata</i>	100	30	Moderate	Growing at toe of slope. Lateral branches forming secondary stems at 10 and 12m. Existing edge tree. Edge adapted and stable. Provides cover for weak alder to the south.	Medium	Retain	Design team to confirm finished grading around perimeter of building 24 will accommodate the critical root zone. The proposed building and grading for landscaping will likely push into the critical root zone of this tree. Arborist supervision is essential during excavations for building foundation, retaining walls, and landscaping.	8.0
Surveyed	869	On Site	Western Hemlock	<i>Tsuga heterophylla</i>	66	30	Moderate	Codominant in group of larger conifers. Acceptable in group. Fair rooting in slope and old stump.	Medium	Retain	This tree can be retained, but it is vulnerable to exposure following removal of 2358. Maintain grades within critical root zone.	4.0
Surveyed	2332	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	62	20	Moderate	Growing between paved driveways. Codominant tree. Midway up slope. Buttress roots on west side. Asymmetrical crown. Stream within north dripline.	Medium	Remove	In conflict with proposed driveway. Removal may affect stability of remaining trees.	3.7
Surveyed	2333	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	53	20	Moderate	Growing between paved driveways. Codominant tree. Midway up slope. Buttress roots on west side. Asymmetrical crown. Stream within north dripline.	Medium	Remove	In conflict with proposed driveway. Removal may affect stability of remaining trees.	3.2

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2334	On Site	Red Alder	Alnus rubra	21	6	Moderate	Growing on slope. Extreme sweep west. Corrected. Asymmetrical crown. Suppressed.	Medium	Retain	Protect and retain.	1.3
Surveyed	2335	On Site	Red Alder	Alnus rubra	14	10	Moderate	Growing on slope. Extreme sweep west. Corrected. Asymmetrical crown.	Medium	Retain	Protect and retain.	0.8
Surveyed	2336	On Site	Red Alder	Alnus rubra	22	16	Moderate	Growing on slope. Extreme sweep west. Corrected.	Medium	Retain	Protect and retain.	1.3
Surveyed	2337	On Site	Western Red Cedar	Thuja plicata	31	25	Moderate	Codominant tree. Extreme sweep. Corrected, asymmetrical crown. Stem fused with 2338. Existing edge tree.	Medium	Wildlife	Not expected to be stable following removal of stronger edge trees. Wildlife tree at safe height. Also will reduce wildfire hazard risk.	1.9
Surveyed	2338	On Site	Western Red Cedar	Thuja plicata	23	18	Moderate	Subordinate tree. Extreme sweep. Corrected, asymmetrical crown. Stem fused with 2337. Existing edge tree.	Medium	Remove	Remove to mitigate wildfire threat.	1.4
Surveyed	2339	On Site	Western Red Cedar	Thuja plicata	35	23	Moderate	Growing on slope. Stream within north dripline. Asymmetrical crown. Dead secondary stem union at 1m, included bark.	Medium	Retain	Maintain existing grading throughout root zone.	2.1
Surveyed	2340	On Site	Western Red Cedar	Thuja plicata	96	30	Moderate	Topped at 20m. Multiple forks at topping. Large buttress roots. Moderate edge tree.	Medium	Retain	Aerial inspection recommended. Will Likely be a lower risk because of the distance to the development.	5.8

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2341	On Site	Western Red Cedar	<i>Thuja plicata</i>	61	25	Moderate	Stream within southern dripline. Stilted roots. Unable to see if topped. Moderate edge tree.	Medium	Retain	This tree may not be stable once exposed.	3.7
Surveyed	2343	On Site	Cascara	<i>Rhamnus purshiana</i>	39	18	Moderate	East phototropic lean. Partially suppressed. Asymmetrical crown.	Medium	Retain	This tree may not be stable once exposed. Outside zone of influence.	2.3
Surveyed	2344	On Site	Cascara	<i>Rhamnus purshiana</i>	28	18	Moderate	East phototropic lean. Suppressed. Asymmetrical crown.	Medium	Retain	This tree may not be stable once exposed. Outside zone of influence.	1.7
Surveyed	2345	On Site	Western Red Cedar	<i>Thuja plicata</i>	50	25	Moderate	Subordinate tree. Asymmetrical crown. Moderate ivy up stem.	Medium	Retain	This tree may not be stable once exposed. Maintain grades and exclude machines from root zone.	3.0
Surveyed	2346	On Site	Western Red Cedar	<i>Thuja plicata</i>	44	30	Moderate	Codominant. Growing on slope. Stream within south dripline. Moderate ivy growth up stem.	Medium	Retain	This tree may not be stable once exposed. Outside zone of influence.	2.6
Surveyed	2347	On Site	Western Red Cedar	<i>Thuja plicata</i>	42	30	Moderate	Codominant. Growing on slope. Stream within south dripline. Moderate ivy growth up stem. Asymmetrical crown. Unable to see top.	Medium	Retain	This tree may not be stable once exposed. Outside zone of influence.	2.5
Surveyed	2348	On Site	Western Red Cedar	<i>Thuja plicata</i>	26	16	Moderate	Suppressed. Symmetrical crown. Growing on slope.	Medium	Retain	Lift prune crown to 5 m.	1.6
Surveyed	2349	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	72	25	Moderate	Topped at 18m. One leader from topping site. Growing on slope.	Medium	Retain	This tree may not be stable once exposed.	4.3
Surveyed	2350	On Site	Western Red Cedar	<i>Thuja plicata</i>	93	30	Moderate	Fork at 18m. Included bark. Growing on slope. Slight westward sweep to stem.	Medium	Retain	Set back from proposed clearing boundary	5.6

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2351	On Site	Western Red Cedar	Thuja plicata	83	39	Moderate	Three stems growing from large rotted nurse stump. Large buttress roots. Growing on slope. All three stems topped at 16m. Main stem forked at 16m.	Medium	Retain	Set back from proposed clearing boundary	5.0
Surveyed	2352	On Site	Western Red Cedar	Thuja plicata	40	30	Moderate	Existing edge tree. Asymmetrical crown. Cannot see top. Moderate ivy growth up stem.	Medium	Retain	Set back from proposed clearing boundary	2.4
Surveyed	2353	On Site	Western Red Cedar	Thuja plicata	76	25	Moderate	Growing on slope. Intermediate tree in stand. Topped at 12m. Multiple leaders from top. Existing edge tree.	Medium	Remove	In conflict with proposed driveway and grading.	4.6
Surveyed	2354	On Site	Big-Leaf Maple	Acer macrophyllum	94	25	Moderate	Growing on slope. Existing paved driveway 1.5m from stem. Multiple stems union at 3m. Appears to have been topped multiple times throughout life.	Medium	Remove	In conflict with proposed road	5.6
Surveyed	2355	City	Western Red Cedar	Thuja plicata	83	25	Moderate	Growing on slope. Existing edge tree. Asymmetrical crown. Existing driveway 1.5m from stem. Recommend survey to determine in on or off site.	Medium	Remove	In conflict with proposed road	5.0
Surveyed	2356	On Site	Western Red Cedar	Thuja plicata	79	25	Moderate	Growing on slope. Single straight stem. Asymmetrical crown. Codominant tree in stand. Existing edge tree.	Medium	Remove	In conflict with proposed road	4.7
Surveyed	2357	On Site	Douglas-Fir	Pseudotsuga menziesii	75	25	Moderate	Growing on slope. Slight sweep to stem. Topped at 20m. Multiple leaders. Intermediate tree in stand.	Medium	Remove	In conflict with site grading.	4.5

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2358	On Site	Western Red Cedar	Thuja plicata	133	30	Good	Growing at toe of slope. Existing edge tree. Single straight stem. Good taper. Well adapted anchor tree for others in row. Retention recommended.	High	Retain	Some conflict with building 2 is expected, approximately 15%. Plan to use blind forms in building construction and minimize over-excavation. The rear-yard retaining structure must be designed and constructed to avoid excavation into root zone; it must be designed in consultation with the project arborist. Arborist supervision is required for all work within critical root zone. Spread 10cm of wood mulch through root zone. Note that this tree is sensitive to construction and may die as a result of the encroachment. Prune tree's crown to maintain 10m clearance from building.	8.0
Surveyed	2359	On Site	Western Hemlock	Tsuga heterophylla	85	30	Good	Growing at toe of slope. Existing edge tree. Single straight stem. Codominant tree in stand. Suitable with neighbouring conifers.	Medium	Retain	Maintain grades within root zone. Protect with tree protection barriers.	6.8

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2360	On Site	Western Red Cedar	Thuja plicata	108	30	Moderate	Strong natural edge tree at toe of slope. Moderate cavity at base acceptable for species. Good potential with adjacent conifers. Retention recommended.	High	Retain	A portion of the root zone will be affected by the retaining wall below Unit 17. Arborist supervision is required during wall construction. Plan to minimize over excavation.	8.6
Surveyed	2361	On Site	Big-Leaf Maple	Acer macrophyllum	100	25	Moderate	Growing at north edge of creek. Stem abutting 2362. Asymmetrical crown,.	Medium	Retain	Arborist to supervise proposed pathway construction within critical root zone.	6.0
Surveyed	2362	On Site	Western Red Cedar	Thuja plicata	67	25	Moderate	Growing at north edge of creek. Stem abutting 2361. Asymmetrical crown,.	Medium	Retain	Arborist to supervise proposed pathway construction within critical root zone.	4.0
Surveyed	2363	On Site	Western Hemlock	Tsuga heterophylla	92	30	Moderate	Growing at toe of slope. Existing edge tree. Single straight stem. Dominant tree in stand. Crown appears thin and slightly stressed. This tree will be sensitive to construction and would require an extra large root protection zone. Suitable at edge.	Medium	Remove	In conflict with proposed building and retaining structures.	9.2
Surveyed	2364	On Site	Western Red Cedar	Thuja plicata	86	25	Moderate	Growing on top on bank of stream. Stem forked at 8m.	Medium	Retain	Arborist to supervise proposed pathway construction within critical root zone.	5.2
Surveyed	2365	On Site	Red Alder	Alnus rubra	23	14	Moderate	Growing at bottom of bank of creek. Swept stem. Corrected.	Medium	Retain	Outside zone of influence.	1.4
Surveyed	2366	On Site	Red Alder	Alnus rubra	17	14	Moderate	Growing at bottom of bank of creek. Swept stem. Corrected.	Medium	Retain	Outside zone of influence.	1.0

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2367	On Site	Western Red Cedar	Thuja plicata	48	18	Poor	Growing on top on bank of stream. Decay column be at base. Topped at 14m.	Low	Retain	Arborist to supervise proposed pathway construction within critical root zone.	2.9
Surveyed	2368	On Site	Western Red Cedar	Thuja plicata	80	25	Moderate	Growing on top on bank of stream. Single straight stem. Asymmetrical crown. Existing edge tree.	Medium	Retain	Arborist to supervise proposed pathway construction within critical root zone.	4.8
Surveyed	2369	On Site	Western Red Cedar	Thuja plicata	104	39	Good	Growing on top on bank of stream. Single straight stem. Symmetrical crown. Existing edge tree.	High	Retain	Arborist to supervise proposed pathway construction within critical root zone.	9.0
Surveyed	2370	On Site	Western Red Cedar	Thuja plicata	28	12	Poor	Suppressed. Significant sweep to stem. Corrected. Asymmetrical crown.	Low	Retain	Can be retained within riparian area, but only with larger cedars adjacent. Maintain grades and exclude machines from critical root zone.	1.7
Surveyed	2371	On Site	Red Alder	Alnus rubra	21	14	Moderate	Growing at bottom of bank of creek. Swept stem. Corrected.	Medium	Retain	Requires cover provided by larger cedars adjacent.	1.3
Surveyed	2372	On Site	Red Alder	Alnus rubra	24	14	Moderate	Growing midway up creek bank. Suppressed.	Medium	Retain	Requires cover provided by larger cedars adjacent.	1.4
Surveyed	2373	On Site	Red Alder	Alnus rubra	15	14	Moderate	Growing midway up creek bank. Suppressed.	Medium	Retain	Requires cover provided by larger cedars adjacent.	0.9
Surveyed	2374	On Site	Red Alder	Alnus rubra	19	20	Moderate	Growing mat top of creek bank. Partially suppressed.	Medium	Retain	Requires cover provided by larger cedars adjacent.	1.1

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2375	On Site	Red Alder	Alnus rubra	25	20	Moderate	Growing at top of creek bank. Partially suppressed. Stem bowed south. Not corrected.	Medium	Retain	Requires cover provided by larger cedars adjacent.	1.5
Surveyed	2376	On Site	Red Alder	Alnus rubra	15	20	Moderate	Growing at top of creek bank. Partially suppressed. Stem bowed south. Not corrected.	Medium	Retain	Requires cover provided by larger cedars adjacent.	0.9
Surveyed	2376	On Site	Red Alder	Alnus rubra	24	20	Moderate	Growing midway on creek bank. Partially suppressed. Stem bowed south. Not corrected.	Medium	Retain	Requires cover provided by larger cedars adjacent.	1.4
Surveyed	2377	On Site	Red Alder	Alnus rubra	36	20	Moderate	Growing at bottom of creek bank. Partially suppressed. Stem bowed south. Not corrected.	Medium	Retain	Requires cover provided by larger cedars adjacent.	2.2
Surveyed	2378	On Site	Red Alder	Alnus rubra	27	20	Moderate	Growing midway on creek bank. Partially suppressed. Stem bowed south. Not corrected.	Medium	Retain	Requires cover provided by larger cedars adjacent.	1.6
Surveyed	2379	On Site	Red Alder	Alnus rubra	39	25	Moderate	Growing at top of creek bank. Dominant Alder in group.	Medium	Retain	Requires cover provided by larger cedars adjacent.	2.3
Surveyed	2380	On Site	Red Alder	Alnus rubra	25	20	Moderate	Growing at top of creek bank. Stem bowed south. Not corrected.	Medium	Retain	Requires cover provided by larger cedars adjacent.	1.5
Surveyed	2432	On Site	Western Red Cedar	Thuja plicata	33	18	Moderate	Subordinate in stand. Asymmetrical crown. Stream within south dripline.	Medium	Retain	Requires cover provided by larger cedars adjacent.	2.0
Surveyed	2441	On Site	Western Red Cedar	Thuja plicata	80	30	Good	Growing on slope. Single straight stem. Symmetrical crown. Dominant tree in stand.	High	Remove	In conflict with proposed building, retaining walls and grading.	4.8

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2442	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	118	40	Good	Growing on slope. Dominant tree in stand. Symmetrical crown. Slight sweep to stem. Unrestricted rooting area. Unable to see top. Good taper and structure. A good candidate for retention.	High	Remove	In conflict with proposed building, walls, and staircase.	9.4
Surveyed	2443	On Site	Western Red Cedar	<i>Thuja plicata</i>	109	30	Poor	Large wound 12m up south side of stem. Decay present. Asymmetrical crown.	Low	Remove	In conflict with proposed building.	6.5
Surveyed	2444	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	92	30	Good	Growing on slope. Single straight stem. Asymmetrical crown. Codominant tree in stand.	High	Remove	In conflict with proposed road	5.5
Surveyed	2445	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	115	30	Good	Existing edge tree. Multiple stems union at base. DBH 85 and 50cm. No inclusion at union. Naturally edge adapted, this is a strong tree and a good candidate for retention.	High	Retain	Design team to confirm finished grading around perimeter of buildings 24 and 25 will accommodate the critical root zone. The proposed building and grading for landscaping will likely push into the critical root zone of this tree. Arborist supervision is essential during excavations for building foundation, retaining walls, and landscaping.	8.1
Surveyed	2446	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	100	30	Moderate	Growing on slope. Asymmetrical crown. Dominant tree in stand. Possibly historic codom break at 10m. Completely occluded.	Medium	Remove	In conflict with required grading.	6.0

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2447	On Site	Western Red Cedar	Thuja plicata	81	30	Moderate	Growing on slope. Large buttress roots. Moderate sweep at base of stem. Corrected. Codominant tree in stand.	Medium	Retain	Design team to confirm finished grading around perimeter of building 19 will accommodate the critical root zone. The proposed building and grading for landscaping will likely push into the critical root zone of this tree. Arborist supervision is essential during excavations for building foundation, retaining walls, and landscaping.	4.9
Surveyed	2448	On Site	Western Red Cedar	Thuja plicata	131	25	Poor	Growing on slope. Large column of decay visible up stem. Stem crooked in multiple places.	Low	Remove	In conflict with proposed building.	7.9
Surveyed	2449	On Site	Western Red Cedar	Thuja plicata	93	30	Good	Growing on slope. Large buttress roots. Single straight stem. Codominant tree in stand. Symmetrical crown.	High	Remove	In conflict with proposed building.	5.6
Surveyed	2450	On Site	Douglas-Fir	Pseudotsuga menziesii	91	30	Moderate	Growing on toe of slope. Single straight stem. Decay visible on north side of stem up 1.5m. Asymmetrical crown. Codominant tree in stand.	Medium	Remove	In conflict with proposed building.	5.5
Surveyed	2451	On Site	Western Red Cedar	Thuja plicata	126	30	Moderate	Growing on slope. Swept stem. Corrected. Asymmetrical crown. Abnormally large root flare. Codominant tree in stand.	Medium	Remove	In conflict with proposed building.	7.6
Surveyed	2452	On Site	Douglas-Fir	Pseudotsuga menziesii	108	30	Good	Growing on slope. Single straight stem. Asymmetrical crown. Dominant tree in stand.	High	Remove	In conflict with proposed building.	6.5

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2453	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	110	30	Good	Growing on slope. Single straight stem. Asymmetrical crown. Dominant tree in stand.	High	Remove	In conflict with proposed building.	6.6
Surveyed	2454	On Site	Western Red Cedar	<i>Thuja plicata</i>	92	30	Moderate	Growing on slope. Asymmetrical crown. Codominant tree in stand.	Medium	Remove	In conflict with required grading.	5.5
Surveyed	2455	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	89	25	Poor	Sitting on large Boulder. Very large buttress root to east. Significant sweep to stem. Corrected. Asymmetrical crown.	Low	Remove	In conflict with proposed road	5.3
Surveyed	2456	On Site	Western Red Cedar	<i>Thuja plicata</i>	101	30	Good	Growing on slope. Single straight stem. Symmetrical crown. Dominant tree in stand.	High	Remove	In conflict with proposed road	6.1
Surveyed	2457	On Site	Western Red Cedar	<i>Thuja plicata</i>	92	25	Poor	Growing on slope. Fork at 20m. Intermediate tree in stand. Large column of decay visible up stem.	Low	Remove	In conflict with required grading.	5.5
Surveyed	2458	On Site	Western Red Cedar	<i>Thuja plicata</i>	134	25	Dying	Extensive decay column throughout stem. Broken top.	Nil	Remove	In conflict with proposed road	8.0
Surveyed	2459	On Site	Western Red Cedar	<i>Thuja plicata</i>	76	25	Moderate	Growing on slope. Single straight stem. Symmetrical crown. Codominant tree in stand. South side of stem fusing with 10cm dbh fir.	Medium	Remove	In conflict with proposed building.	4.6
Surveyed	2461	On Site	Western Red Cedar	<i>Thuja plicata</i>	105	30	Good	Growing on slope. Large buttress roots. Single straight stem. Symmetrical crown. Codominant tree in stand.	Medium	Remove	In conflict with proposed building, retaining walls and grading.	6.3

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2462	On Site	Western Red Cedar	Thuja plicata	77	30	Moderate	Growing on slope. Large buttress roots. Slight sweep at base of stem. Asymmetrical crown. Codominant tree in stand.	Medium	Remove	In conflict with proposed building.	4.6
Surveyed	2463	On Site	Western Red Cedar	Thuja plicata	107	30	Good	Growing on slope. Single straight stem. Symmetrical crown. Dominant tree in stand.	High	Remove	In conflict with proposed road, building.	6.4
Surveyed	2465	On Site	Douglas-Fir	Pseudotsuga menziesii	83	25	Poor	Topped at 18m. Multiple leaders. Intermediate tree in stand. Existing driveway 2m north of stem.	Low	Remove	In conflict with building envelope	5.0
Surveyed	2466	On Site	Douglas-Fir	Pseudotsuga menziesii	78	39	Moderate	Growing on slope. Existing paved driveway 1.5m north of stem. Appears to have been historically topped at 8m. One leader. Codominant tree in stand.	Medium	Remove	In conflict with proposed building envelope.	4.7
Surveyed	2467	On Site	Douglas-Fir	Pseudotsuga menziesii	94	30	Moderate	Growing on slope. Codominant tree. Stem forked at 20m. Moderate ivy growth up stem.	Medium	Retain	Outside zone of influence.	5.6
Surveyed	2468	On Site	Western Red Cedar	Thuja plicata	115	30	Moderate	Growing on slope. Codominant tree. Stem forked at 18m.	Medium	Retain	Outside zone of influence.	6.9
Surveyed	2469	On Site	Western Red Cedar	Thuja plicata	92	30	Moderate	Growing on slope. Codominant tree. Asymmetrical crown. Main stem enveloping smaller stem at 2.5m. Heavy inclusion. Unable to see if topped.	Medium	Retain	Outside zone of influence.	5.5
Surveyed	2470	On Site	Western Red Cedar	Thuja plicata	85	30	Moderate	Growing on slope. Dominant tree. Asymmetrical crown. Main stem enveloping smaller stem at 2.5m. Heavy inclusion.	Medium	Retain	Outside zone of influence.	5.1

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2471	On Site	Douglas-Fir	Pseudotsuga menziesii	91	30	Moderate	Growing on slope. Possible restricted rooting from large boulders in dripline. Single straight stem. Cannot see top. Codominant tree in stand.	Medium	Retain	Maintain grades within root zone.	5.5
Surveyed	2472	On Site	Douglas-Fir	Pseudotsuga menziesii	98	30	Good	Growing on slope. Codominant tree in stand. Symmetrical crown. Unrestricted rooting area. Unable to see top.	High	Retain	Maintain grades within root zone.	5.9
Surveyed	2473	On Site	Douglas-Fir	Pseudotsuga menziesii	93	30	Good	Growing on slope. Codominant tree in stand. Symmetrical crown. Existing edge tree. Slight sweep to stem. Unable to see top.	High	Retain	Some conflict with proposed road. Retaining this tree requires that road cut be designed to minimize slope. Retaining wall or shotcrete may be required.	9.0
Surveyed	2474	On Site	Douglas-Fir	Pseudotsuga menziesii	91	30	Good	Growing on slope. Codominant tree in stand. Symmetrical crown. Existing edge tree. Bird nest up 10m on south side. Unknown if active or of what species. Slight sweep to stem. Unable to see top.	High	Remove	In conflict with proposed road.	5.5
Surveyed	2475	On Site	Douglas-Fir	Pseudotsuga menziesii	103	45	Moderate	Growing on slope. Slight sweep to stem. Large symmetrical crown. Existing edge tree. Strongly rooted and naturally edge adapted this is a good anchor tree for the riparian area. Previously topped. New attachments look okay from the ground but should be inspected aerially if planning to retain adjacent to dwellings.	High	Retain	Given 8x root zone because of slope. Maintain grades within root zone. A climber should inspect unions and prune as necessary.	8.2

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	2490	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	91	40	Good	Large dominant tree at crest of slope. Towers over surrounding stand. A good anchor tree for riparian setback area.	High	Remove	In conflict with proposed road	5.5
Surveyed	2664	On Site	Western Red Cedar	<i>Thuja plicata</i>	86	30	Good	Edge tree with asymmetrical crown north. Mother root zone is compacted gravel and about 1.5m higher than the south side.	Medium	Remove	In conflict with proposed road, grading and walls.	5.2
Surveyed	7201	On Site	Western Red Cedar	<i>Thuja plicata</i>	64	23	Moderate	Natural edge tree at south end of hedgerow. Located at top of ditch west side. Good taper. Deep crown.	Medium	Retain	Retain hedgerow. Works on east side of existing ditch will be acceptable.	3.8
Surveyed	7202	On Site	Western Red Cedar	<i>Thuja plicata</i>	55	23	Moderate	Natural edge tree at south end of hedgerow. Located at top of ditch west side. Good taper. Deep crown. Forms good screen for neighbouring property.	Medium	Retain	Retain hedgerow. Works on east side of existing ditch will be acceptable.	3.3
Surveyed	7203	On Site	Western Red Cedar	<i>Thuja plicata</i>	63	NA	Moderate	Codominant in hedge row. Major sweep in base. Corrected. Base 203m west of ditch,.	Medium	Retain	Retain hedgerow. Works on east side of existing ditch will be acceptable.	3.8
Surveyed	7204	On Site	Western Red Cedar	<i>Thuja plicata</i>	43	20	Moderate	Natural edge tree at south end of hedgerow. Located at top of ditch west. Smaller intermediate tree. Required rest of hedge row for stability.	Medium	Retain	Retain hedgerow. Works on east side of existing ditch will be acceptable.	2.6
Surveyed	7205	On Site	Western Red Cedar	<i>Thuja plicata</i>	75	23	Good	Dominant with deep crow. Good buttress. 2.5m from top of ditch. Codom from 2m. Good attachment.	Medium	Retain	Retain hedgerow. Works on east side of existing ditch will be acceptable.	4.5

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7206	On Site	Western Red Cedar	Thuja plicata	30	18	Moderate	Group of three similar trees. Weak unions. Suppressed but acceptable in hedge.	Medium	Retain	Retain hedgerow. Works on east side of existing ditch will be acceptable.	1.8
Surveyed	7207	On Site	Western Red Cedar	Thuja plicata	20	18	Poor	Suppressed but acceptable in hedge.	Medium	Retain	Retain hedgerow. Works on east side of existing ditch will be acceptable.	1.2
Surveyed	7208	On Site	Western Red Cedar	Thuja plicata	25	18	Poor	Suppressed but acceptable in hedge.	Low	Retain	Retain hedgerow. Works on east side of existing ditch will be acceptable.	1.5
Surveyed	7214	City	Western Hemlock	Tsuga heterophylla	30	15	Moderate	South end of hedgerow. All moderate hemlocks on west side of ditch, near road. Vulnerable to changes in road width and ditch location.	Medium	Remove	A portion of this hedgerow will need to be removed to accommodate the new road.	1.8
Surveyed	7215	City	Western Hemlock	Tsuga heterophylla	30	15	Moderate	South end of hedgerow. All moderate hemlocks on west side of ditch, near road. Vulnerable to changes in road width and ditch location.	Medium	Remove	A portion of this hedgerow will need to be removed to accommodate the new road.	1.8
Surveyed	7216	On Site	Red Alder	Alnus rubra	34	20	Good	Young. Vigorous. Growing close to ditch. Venerable to changes to driveway.	Medium	Remove	Will not tolerate changes to stream and road.	2.0
Surveyed	7217	On Site	Western Red Cedar	Thuja plicata	17	12	Good	Young. Vigorous. Tree between road and ditch. Good potential if grade can be maintained.	Medium	Retain	Design rearing pools outside of tree's critical root zone. Arborist to monitor rearing pool construction.	1.0
Surveyed	7218	On Site	Red Alder	Alnus rubra	27	12	Good	Young. Vigorous. Tree west side of ditch. Good potential if grade can be maintained.	Medium	Retain	Design rearing pools outside of tree's critical root zone. Arborist to monitor rearing pool construction.	1.6

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7219	On Site	Red Alder	<i>Alnus rubra</i>	24	12	Good	Young. Vigorous. Tree west side of ditch. Good potential if grade can be maintained. Moderate ivy.	Medium	Retain	Design rearing pools outside of tree's critical root zone. Arborist to monitor rearing pool construction.	1.4
Unsurveyed	7220	On Site	Western Red Cedar	<i>Thuja plicata</i>	64	20	Moderate	Large buttress roots. Saturated ground. Good structure.	Medium	Retain	Design rearing pools outside of tree's critical root zone. Arborist to monitor rearing pool construction.	3.8
Surveyed	7221	On Site	Red Alder	<i>Alnus rubra</i>	32	14	Moderate	Intermediate tree. Saturated ground. Requires 7220 for stability.	Low	Retain	Maintain grades in root zone, avoid root zone when constructing habitat compensation.	1.9
Surveyed	7222	On Site	Western Red Cedar	<i>Thuja plicata</i>	47	26	Moderate	Large buttress roots. Saturated ground. Good structure.	Medium	Retain	Design rearing pools outside of tree's critical root zone. Arborist to monitor rearing pool construction.	2.8
Surveyed	7223	On Site	Big-Leaf Maple	<i>Acer macrophyllum</i>	60	25	Moderate	Tall straight single stem. Moderate crown. Asymmetrical crown. Exposed possibly 5 years ago. Appears stable. Assessment limited. Inaccessible. Not tagged.	Medium	Retain	Design rearing pools outside of tree's critical root zone. Arborist to monitor rearing pool construction.	3.6
Surveyed	7224	Off Site	Western Red Cedar	<i>Thuja plicata</i>	70	20	Good	Open grown. Large crown. Amazing tree house bolted to stem. Assessment limited. Inaccessible.	High	Retain	Maintain grades in root zone, avoid root zone when constructing habitat compensation.	4.2
Surveyed	7225	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	64	NA	Good	Open grown. Good stem structure. Unrestricted rooting. Good candidate for retention.	High	Retain	Maintain grades within root zone.	3.8

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7226	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	24	18	Moderate	Subordinate to but acceptable with 7225.	Medium	Retain	Maintain grades in root zone, avoid root zone when constructing habitat compensation.	1.4
Surveyed	7227	On Site	Western Red Cedar	<i>Thuja plicata</i>	56	18	Good	Best if kept with 7225. Acceptable on own. Good taper. Asymmetrical crown.	Medium	Retain	Maintain grades in root zone, avoid root zone when constructing habitat compensation.	3.4
Surveyed	7228	On Site	Bitter Cherry	<i>Prunus emarginata</i>	22	10	Good	Young. Good within area.	Medium	Retain	Maintain grades in root zone, avoid root zone when constructing habitat compensation.	1.3
Surveyed	7229	On Site	Big-Leaf Maple	<i>Acer macrophyllum</i>	32	20	Moderate	Young and open grown. Minor decay at base.	Medium	Retain	Maintain grades in root zone, avoid root zone when constructing habitat compensation.	1.9
Surveyed	7230	On Site	Big-Leaf Maple	<i>Acer macrophyllum</i>	40	20	Moderate	Cop pics of three stems with other vegetation mixed within. Protect to dripline. 4m.	Medium	Retain	Maintain grades in root zone, avoid root zone when constructing habitat compensation.	2.4
Surveyed	7231	On Site	Red Alder	<i>Alnus rubra</i>	67	24	Moderate	Large mature with good structure. Requires large root zone. Will be venerable to work within root zone. Beginnings of crown die back.	Medium	Retain	Maintain grades in root zone, avoid root zone when constructing habitat compensation.	4.0
Surveyed	7232	Off Site	Red Alder	<i>Alnus rubra</i>	34	23	Dying	Dying alder. Recommend survey to determine location.	Nil	Retain	With riparian area. A poor tree but expected to be low risk. Reassess.	2.0
Surveyed	7233	Off Site	Red Alder	<i>Alnus rubra</i>	63	23	Poor	Two stems. Heavy inclusion. Historic crown failures. Recommend convert to wildlife as 4m.	Low	Retain	With riparian area. A poor tree but expected to be low risk. Reassess.	3.8

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7234	Off Site	Big-Leaf Maple	Acer macrophyllum	55	20	Moderate	Single straight stem. Well adapted to opening to north. Moderate ivy should be removed. Southern portion of root zone at shoulder of driveway. Review grading plan.	Medium	Retain	Protect and retain.	3.3
Surveyed	7235	On Site	Western Hemlock	Tsuga heterophylla	23	14	Poor	Rooted in nurse stump. Damaged roots. Not recommend for retention.	Low	Remove	Remove to mitigate wildfire threat. Will not be stable and will pose a hazard to proposed development. Removal recommended.	1.4
Surveyed	7236	On Site	Western Red Cedar	Thuja plicata	70	20	Good	Straight stem. Good taper. Unrestricted rooting. Exploring options to retain this tree would be worthwhile.	High	Remove	Remove to mitigate wildfire threat. In conflict with proposed walls and grading.	4.2
Surveyed	7237	On Site	Cascara	Rhamnus purshiana	21	8	Poor	Asymmetrical crown. Suppressed by adjacent spacecraft. Only acceptable with cedar .	Low	Remove	In conflict with building 6/7 development	1.3
Surveyed	7238	On Site	Big-Leaf Maple	Acer macrophyllum	21	8	Poor	Not suitable for exposure. Poor health and structure.	Low	Remove	Removal recommended to stabilize edge. Location uncertain - may be within 10m setback.	1.3
Surveyed	7239	On Site	Big-Leaf Maple	Acer macrophyllum	21	8	Poor	Not suitable for exposure. Poor health and structure. Decay at base.	Nil	Remove	Removal recommended to stabilize edge. Location uncertain - may be within 10m setback.	1.3
Surveyed	7240	On Site	Big-Leaf Maple	Acer macrophyllum	21	8	Poor	Not suitable for exposure. Poor structure. Asymmetrical crown.	Low	Remove	Removal recommended to stabilize edge. Location uncertain - may be within 10m setback.	1.3
Surveyed	7241	On Site	Big-Leaf Maple	Acer macrophyllum	29	20	Poor	Extreme sweep in base. Extensive decay throughout stem.	Nil	Remove	Removal recommended to stabilize edge. Location uncertain - may be within 10m setback.	1.7

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7242	On Site	Western Hemlock	Tsuga heterophylla	35	NA	Moderate	Intermediate in stand. Can only be retained with larger trees. Asymmetrical crown. Sweep in base. Corrected.	Medium	Remove	Remove to mitigate wildfire threat. Removal recommended to stabilize edge. Location uncertain - may be within 10m setback.	2.1
Surveyed	7243	On Site	Big-Leaf Maple	Acer macrophyllum	52	25	Moderate	Multiple stems with good unions. Asymmetrical crown. Could only be retained if entire adjacent group retained. Biased to west.	Low	Remove	Removal recommended to stabilize edge. Location uncertain - may be within 10m setback.	3.1
Surveyed	7244	On Site	Western Red Cedar	Thuja plicata	75	27	Good	A large codominant tree. Good taper and structure. Exposed to west. A good candidate for retention, especially with adjacent large cedars.	High	Remove	In conflict with grading and building envelope.	4.5
Surveyed	7245	On Site	Western Red Cedar	Thuja plicata	66	20	Good	Good taper. Straight stem. Good candidate for retention with adjacent trees.	High	Remove	In conflict with proposed building	6.6
Surveyed	7246	On Site	Western Red Cedar	Thuja plicata	84	20	Good	Good taper. Deep crown. Has leader wobble. Suitable for retention alone.	High	Remove	In conflict with proposed building envelope.	8.4
Surveyed	7247	On Site	Red Alder	Alnus rubra	29	18	Moderate	Intermediate in stand growing in wet soil. Moderate vigour. Not suitable for exposure.	Low	Remove	Conflicts with grading and retaining wall construction	0.0
Surveyed	7248	On Site	Western Red Cedar	Thuja plicata	20	12	Moderate	Young healthy tree. Too small to pose risk.	Medium	Remove	in conflict with retaining wall and wetland construction	1.2
Surveyed	7249	On Site	Red Alder	Alnus rubra	60	18	Moderate	Intermediate in stand growing in wet soil. Moderate vigour. Not suitable for exposure. Two equal sized stems. Phototropic lean west.	Low	Remove	Removal recommended to stabilize edge. Location uncertain - may be within 10m setback.	3.6

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7250	On Site	Red Alder	Alnus rubra	27	18	Moderate	Intermediate in stand growing in wet soil. Moderate vigour. Not suitable for exposure. Two stems. Phototropic lean west.	Low	Wildlife	Not suitable for exposure at edge. Likely to fail. Wildlife at safe height.	1.6
Surveyed	7251	On Site	Red Alder	Alnus rubra	37	20	Moderate	Mature codominant. Phototropic lean west. Sensitive to site changes due to age. Wildlife.	Low	Wildlife	Not suitable for exposure at edge. Likely to fail. Wildlife at safe height.	2.2
Surveyed	7252	On Site	Red Alder	Alnus rubra	38	20	Moderate	Mature codominant. Phototropic lean west. Sensitive to site changes Europe to age. Wildlife.	Low	Wildlife	Not suitable for exposure at edge. Likely to fail. Wildlife at safe height.	2.3
Surveyed	7253	On Site	Red Alder	Alnus rubra	38	20	Moderate	Mature codominant. Phototropic lean west. Sensitive to site changes due to age. Wildlife.	Low	Wildlife	Not suitable for exposure at edge. Likely to fail. Wildlife at safe height.	2.3
Surveyed	7254	On Site	Western Red Cedar	Thuja plicata	38	16	Good	Young tree. Somewhat suppressed. Long term potential.	High	Remove	Remove to mitigate wildfire threat. Removal recommended to stabilize edge. Location uncertain - may be within 10m setback.	2.3
Surveyed	7255	On Site	Red Alder	Alnus rubra	27	15	Moderate	Mature codominant. Phototropic lean west. Sensitive to site changes due to age. Broken top. Wildlife.	Low	Wildlife	Not suitable for exposure. Wildlife to safe height.	1.6
Surveyed	7256	On Site	Red Alder	Alnus rubra	46	30	Moderate	Mature codominant. Phototropic lean west. Sensitive to site changes due to age. Wildlife if possible.	Low	Remove	In conflict with road.	2.8
Surveyed	7257	On Site	Red Alder	Alnus rubra	41	20	Poor	Phototropic lean west. Sensitive to site changes due to age. Unstable rooting. Wildlife if possible.	Low	Remove	In conflict with road	2.5

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7258	On Site	Red Alder	<i>Alnus rubra</i>	26	20	Poor	Phototropic lean west. Sensitive to site changes due to age. Unstable rooting. Wildlife if possible.	Low	Remove	In conflict with road	1.6
Unsurveyed	7259	On Site	Big-Leaf Maple	<i>Acer macrophyllum</i>	38	12	Poor	Broken top. Multiple poorly attach leaders.	Low	Remove	In conflict with road	2.3
Surveyed	7260	On Site	Red Alder	<i>Alnus rubra</i>	22	15	Moderate	Young pole. Pistol butt. Weak rooting in wet soil.	Low	Remove	In conflict with road	1.3
Surveyed	7261	On Site	Red Alder	<i>Alnus rubra</i>	44	25	Moderate	Average codominant. Somewhat adapted to opening at west. Heavy ivy.	Low	Remove	Not suitable for exposure at edge. Likely to fail. Wildlife at safe height. Conflicts with building C envelope	2.6
Surveyed	7262	On Site	Western Red Cedar	<i>Thuja plicata</i>	42	17	Moderate	Intermediate tree. Rooting in soft saturated soil.	Medium	Remove	In conflict with road.	2.5
Surveyed	7263	On Site	Western Red Cedar	<i>Thuja plicata</i>	29	12	Moderate	Rooting in saturated soils. Moderate form. Good riparian tree, too small to be risk.	Low	Remove	In conflict with road	1.7
Surveyed	7264	On Site	Western Hemlock	<i>Tsuga heterophylla</i>	39	14	Moderate	Open grown, moderate structure. Rooting in soft saturated ground.	Medium	Remove	In conflict with road	2.3
Surveyed	7265	On Site	Red Alder	<i>Alnus rubra</i>	24	14	Poor	East lean. Rooting in soft saturated soils. Stem broken at 7m.	Low	Remove	Will not be stable and will pose a hazard to proposed development. Removal recommended.	1.4
Surveyed	7266	On Site	Western Hemlock	<i>Tsuga heterophylla</i>	20	12	Moderate	Young intermediate.	Medium	Retain	Small tree will not pose a risk. Maintain grades within root zone.	1.2

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7270	On Site	Red Alder	<i>Alnus rubra</i>	72	30	Moderate	Large mature alders growing as pair of equal 36cm stems. Strong phototropic lean north to neighbouring property. On margin of setback area. Not recommended for retention without cover of stand to south.	Medium	Remove	In conflict with proposed road	4.3
Surveyed	7271	On Site	Western Red Cedar	<i>Thuja plicata</i>	63	30	Good	Codominant in dense stand of conifers. Asymmetrical crown north. Needs support of surrounding stand.	Medium	Remove	Remove to mitigate wildfire threat. In conflict with proposed road	3.8
Surveyed	7272	On Site	Western Red Cedar	<i>Thuja plicata</i>	51	30	Moderate	Codominant in stand. Limited taper. Moderate decay at base. Needs surrounding trees for stability.	Low	Remove	In conflict with proposed road	3.1
Surveyed	7274	On Site	Western Red Cedar	<i>Thuja plicata</i>	33	25	Moderate	Intermediate tree with very asymmetrical crown, biased west. Retention without 2763 is not recommended.	Low	Remove	Remove to mitigate wildfire threat. Will not be stable following removal of trees to south. Removal recommended to mitigate hazard.	2.0
Surveyed	7275	On Site	Western Red Cedar	<i>Thuja plicata</i>	56	25	Poor	Weak base with pistol butt and decay. Intermediate in stand. Not a good edge tree.	Low	Remove	Remove to mitigate wildfire threat. Will not be stable following removal of trees to south. Removal recommended to mitigate hazard.	3.4

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7276	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	62	30	Good	Relatively dominant. Crooked stem from past injury. One of the only available edge trees.	Medium	Retain	Plan to avoid excavations into root zone. Blind forming may be required. Arborist to supervise foundation excavations. The loss of this edge tree would have cascading effects and require the removal of additional trees within riparian setback area. Cover root zone with 10cm of wood mulch.	5.0
Surveyed	7280	On Site	Western Hemlock	<i>Tsuga heterophylla</i>	25	25	Poor	Suppressed. Weak rooting. Leans north.	Nil	Remove	Remove to mitigate wildfire threat. Unsuitable for retention due to condition	1.5
Surveyed	7281	On Site	Western Red Cedar	<i>Thuja plicata</i>	77	35	Moderate	Good taper and vigour. Candelabra top from past topping may be salvageable. Requires pruning. Not a strong edge tree but the only available option at 10m setback.	Medium	Retain	Plan to avoid excavations into root zone. Blind forming may be required. Arborist to supervise foundation excavations. The loss of this edge tree would have cascading effects and require the removal of additional trees within riparian setback area. Cover root zone with 10cm of wood mulch.	4.6

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7282	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	63	35	Moderate	Good taper and vigour. Crooked top from past pruning appears to have sealed and has tolerable structure. Not a strong edge tree but the only available option at 10m setback.	Medium	Retain	Plan to avoid excavations into root zone. Blind forming may be required. Arborist to supervise foundation excavations. The loss of this edge tree would have cascading effects and require the removal of additional trees within riparian setback area. Cover root zone with 10cm of wood mulch.	3.8
Surveyed	7283	On Site	Western Red Cedar	<i>Thuja plicata</i>	56	35	Good	Decent codominant tree with single straight stem and moderate crown, good taper. Tall.	Medium	Retain	Plan to avoid excavations into root zone. Blind forming may be required. Arborist to supervise foundation excavations. The loss of this edge tree would have cascading effects and require the removal of additional trees within riparian setback area. Cover root zone with 10cm of wood mulch.	3.4
Surveyed	7284	On Site	Western Red Cedar	<i>Thuja plicata</i>	27	15	Moderate	Small, suppressed tree with limited taper and deep crown. May be structurally sound but will be sensitive to increased solar exposure on south slope.	Low	Remove	Remove to mitigate wildfire threat. Not expected to survive exposure and grading to accommodate parking spots.	1.6
Surveyed	7285	Off Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	35	25	Moderate	Younger codominant with good structure. Emergent crown. Limited taper, but not too tall to retain.	Medium	Retain	NA	2.1

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7286	Off Site	Paper Birch	Betula papyrifera	45	15	Good	Healthy coppice of 6 equal stems.	Medium	Retain	NA	2.7
Surveyed	7287	On Site	Western Red Cedar	Thuja plicata	24	20	Moderate	Small, suppressed tree with limited taper and deep crown. May be structurally sound but will be sensitive to increased solar exposure on south slope.	Low	Retain	May decline. Retain and monitor. Irrigation system will improve retention outcome.	1.4
Surveyed	7288	On Site	Western Red Cedar	Thuja plicata	69	35	Good	Tall, edge adapted tree beside watercourse. Deep crown. Moderate taper.	Medium	Retain	preserve existing grades within root zone. Lift prune crown to 5 m.	4.1
Surveyed	7673	On Site	Douglas-Fir	Pseudotsuga menziesii	74	30	Moderate	Dominant edge tree is a fair candidate for retention. Previously topped. Aerial inspection of wound recommended if target within 20m. Root zone slopes steeply to west, and is interrupted by cutslope and ditch on low side. About 2m below. Provides cover for weaker cedars closer to stream.	Medium	Retain	Plan to avoid excavations into root zone. Blind forming may be required. Arborist to supervise foundation excavations. The loss of this edge tree would have cascading effects and require the removal of additional trees within riparian setback area. Cover root zone with 10cm of wood mulch.	4.4
Surveyed	7675	On Site	Douglas-Fir	Pseudotsuga menziesii	64	30	Dead	Spongy snag with conks. Hazard to future development.	Nil	Remove	NA	3.8
Unsurveyed	7277a	On Site	Western Red Cedar	Thuja plicata	42	8	Moderate	Topped for line clearance. Growing in group. Rooting in soft soil. Acceptable for retention in wetland area.	Medium	Remove	Remove to mitigate wildfire threat. In conflict with proposed grading and retaining wall.	2.5

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7277b	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	42	30	Good	Relatively dominant. Crooked stem from past injury. One of the only available edge trees. Possible tagging error. Spiral prune if retaining.	Medium	Retain	Plan to avoid excavations into root zone. Blind forming may be required. Arborist to supervise foundation excavations. The loss of this edge tree would have cascading effects and require the removal of additional trees within riparian setback area. Cover root zone with 10cm of wood mulch. Spiral prune.	3.4
Unsurveyed	7278a	On Site	Western Red Cedar	<i>Thuja plicata</i>	40	8	Moderate	Topped for line clearance. Growing in group. Rooting in soft soil. Acceptable for retention in wetland area.	Medium	Remove	Remove to mitigate wildfire threat. In conflict with proposed grading and retaining wall.	2.4
Surveyed	7278b	On Site	Douglas-Fir	<i>Pseudotsuga menziesii</i>	62	30	Moderate	Average codominant. Crooked stem from past topping. One of the only available edge trees. Aerial inspection recommended.	Medium	Retain	Engineer to review grading requirements around road to confirm that excavations will not extend into critical root zone. Arborist to supervise grading for road. The loss of this edge tree would have cascading effects and require the removal of additional trees within riparian setback area.	3.7
Unsurveyed	7279a	On Site	Western Red Cedar	<i>Thuja plicata</i>	12	10	Moderate	Growing in group. Rooting in soft soil. Acceptable for retention in wetland area.	Medium	Remove	Remove to mitigate wildfire threat. In conflict with proposed grading and retaining wall.	0.7

Surveyed?	Tag #	Location	Species Common Name	Botanical Name	DBH (cm)	Height (m)	Health and Structure Rating	Comments	Retention Value Rating	Retain/ Remove	Retention/TPZ Comments	*TPZ (m)
Surveyed	7279b	On Site	Western Red Cedar	Thuja plicata	55	30	Moderate	Codominant in stand. Two tops with fair union at old topping injury. Moderate taper, small crown.	Medium	Retain	Preserve existing grades within root zone.	3.3
Surveyed	OS01	Off Site	Western Red Cedar	Thuja plicata	70	20	Good	Open grown. Full crown. Driveway within south dripline.	High	Retain	Outside zone of influence	4.2
Surveyed	Os5674	Off Site	Western Red Cedar	Thuja plicata	104	20	Moderate	Large open grown tree prominent on neighbouring property. Multiple stems, but good crown. Root zone extends to ditch.	High	Retain	Build fences at edge of shoulder. Minor encroachment for road work expected withing root zone.	10.4

Appendix 2 Site Photographs



Photo 1. Overhead view of the subject area's canopy. Note transition between deciduous stand at lower elevations and the conifers on the slope. Also note significant Douglas fir at right of frame. (probably tree #2452)




Photo 2. Overhead view of the southwest corner of the site at Daffodil Drive, The ditch is obscured, but the row of offsite trees is visible west (below) the road.



Photo 3. The middle of the site is a dense mix of native conifers with a closed canopy.



Photo 4. Typical crowns of conifers within the site. These trees have grown in a competitive environment and typically have small crowns and slender stems.



Photo 5. The existing asphalt road / easement at the top of the site



Photo 6. The riparian setback for the tributary. Much of the setback is a gravel road and shoulder, although many small deciduous trees fall within the setback area.



Photo 7. Looking south down the existing gravel driveway. Note open grown crowns of smaller trees along the property line.

Appendix 3 Tree Health and Structure Rating Criteria

The tree health and structure ratings used by Diamond Head Consulting summarize each tree based on both positive and negative attributes using five stratified categories. These ratings indicate health and structural conditions that influence a tree's ability to withstand local site disturbance during the construction process (assuming appropriate tree protection) and benefit a future urban landscape.

Excellent: Tree of possible specimen quality, unique species or size with no discernible defects.

Good: Tree has no significant structural defects or health concerns, considering its growing environment and species.

Moderate: Tree has noted health and/or minor to moderate structural defects. This tree can be retained, but may need mitigation (e.g., pruning or bracing) and monitoring post-development. A moderate tree may be suitable for retention within a stand or group, but not suitable on its own.

Poor: Tree is in serious decline from previous growth habit or stature, has multiple defined health or structural weaknesses. It is unlikely to acclimate to future site use change. This tree is not suitable for retention within striking distance of most targets.

Dying/Dead: Tree is in severe decline, has severe defects or was found to be dead.

Appendix 4 Tree Retention Value Rating Criteria

The tree retention value ratings used by Diamond Head Consulting provide guidance for tree retention planning. Each tree in an inventory is assigned to one of four stratified categories that reflect its value as a future amenity and environmental asset in a developed landscape. Tree retention value ratings take in to account the health and structure rating, species profile*, growing conditions and potential longevity assuming a tree's growing environment is not compromised from its current state.

High: Tree suitable for retention. Has a good or excellent health and structure rating. Tree is open grown, an anchor tree on the edge of a stand or dominant within a stand or group. Species of *Populus*, *Alnus* and *Betula* are excluded from this category.

Medium: Tree suitable for retention with some caveats or suitable within a group**. Tree has moderate health and structure rating, but is likely to require remedial work to mitigate minor health or structural defects. Includes trees that are recently exposed, but wind firm, and trees grown on sites with poor rooting environments that may be ameliorated.

Low: Tree has marginal suitability for retention. Health and structure rating is moderate or poor; remedial work is unlikely to be viable. Trees within striking distance of a future site developments should be removed.

Nil: Tree is unsuitable for retention. It has a dying/dead or poor health and structure rating. It is likely that the tree will not survive, or it poses an unacceptable hazard in the context of future site developments.

* The species profile is based upon mature age and height/spread of the species, adaptability to land use changes and tree species susceptibility to diseases, pathogen and insect infestation.

** Trees that are 'suitable as a group' have grown in groups or stands that have a single, closed canopy. They have not developed the necessary trunk taper, branch and root structure that would allow them to be retained individually. These trees should only be retained in groups.

Appendix 5 Risk Rating Matrices

Trees with a *probable* or *imminent* likelihood of failure, a *medium* or *high* likelihood of impacting a specified target, and a *significant* or *severe* consequence of failure have been assessed for risk and included in this report (Section 3.2). These two risk rating matrices showing the categories used to assign risk are taken without modification to their content from the International Society of Arboriculture Tree Risk Assessment Qualification Manual.

Matrix 1: Likelihood

Likelihood of Failure	Likelihood of Impacting Target			
	Very Low	Low	Medium	High
Imminent	Unlikely	Somewhat Likely	Likely	Very Likely
Probable	Unlikely	Unlikely	Somewhat Likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat Likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2: Risk Rating

Likelihood of Failure and Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very Likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat Likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low

Appendix 6 Construction Guidelines

Tree management recommendations in this report are made under the expectation that the following guidelines for risk mitigation and proper tree protection will be adhered to during construction.

Respecting these guidelines will prevent changes to the soil and rooting conditions, contamination due to spills and waste, or physical wounding of the trees. Any plans for construction work and activities that deviate from or contradict these guidelines should be discussed with the project arborist so that mitigation measures can be implemented.

Tree protection Zones

Tree protection zones (TPZs) are specifically intended to protect a tree's roots from negative construction impacts. TPZs are required to retain good health and vigor of the tree during development and in the future landscape. The TPZ boundary is measured as a radius in all directions from the outer surface of the tree's stem. The TPZ radius is determined by the extent of tree protection zones according to local municipal bylaw specifications and may be modified based on professional judgement of the project arborist to accommodate species specific tolerances and site specific growing conditions.

Tree Protection Zones

Tree protection zones (TPZs) are fenced areas around the recommended TPZ. Within a TPZ, no construction activity, including materials storage, grading or landscaping, may occur without project arborist approval. Within the TPZ, the following are tree preservation guidelines based on industry standards for best practice and local municipal requirements:

- No soil disturbance or stripping.
- Maintain the natural grade.
- No storage, dumping of materials, parking, underground utilities or fires within TPZs or tree driplines.
- Any planned construction and landscaping activities affecting trees should be reviewed and approved by a consulting arborist.
- Install specially designed foundations and paving when these structures are required within TPZs.
- Route utilities around TPZs.
- Excavation within the TPZs should be supervised by a consultant arborist.
- Surface drainage should not be altered in such a way that water is directed in or out of the TPZ.
- Site drainage improvements should be designed to maintain the natural water table levels within the TPZ.

Tree Protection Fences

Prior to any construction activity, tree protection fences must be constructed at the root protection zone perimeter. The protection barrier or temporary fencing must be at least 1.2 m in height and constructed of 2" by 4" lumber with orange plastic mesh screening. Tree protection fences must be

constructed prior to tree removal, excavation or construction and remain intact throughout the entire duration of construction.

Tree Crown Protection and Pruning

All heavy machinery (excavators, cranes, dump trucks, etc.) working within five meters of a tree's crown should be made aware of their proximity to the tree. If there is to be a sustained period of machinery working within five meters of a tree's crown, a line of colored flags should be suspended at eye-level of the machinery operator for the length of the protected tree area. Any concerns regarding the clearance required for machinery and workers within or immediately outside tree protection zones should be referred to the project arborist so that a zone surrounding the crowns can be established or pruning measures undertaken. Any wounds incurred to protected trees during construction should be reported to the project arborist immediately.

Unsurveyed Trees

Unsurveyed trees identified by DHC in the Tree Retention Plan have been hand plotted for approximate location only using GPS coordinates and field observations. The location and ownership of unsurveyed trees cannot be confirmed without a legal survey. The property owner or project developer must ensure that all relevant on- and off-site trees are surveyed by a legally registered surveyor, whether they are identified by DHC or not.

Removal of logs from sites

Private timber marks are required to transport logs from privately-owned land in BC. It is property owner's responsibility to apply for a timber mark prior to removing any merchantable timber from the site. Additional information can be found at: <http://www.for.gov.bc.ca/hth/private-timber-marks.htm>

Regulation of Soil Moisture and Drainage

Excavation and construction activities adjacent to TPZs can influence the availability of moisture to protected trees. This is due to a reduction in the total root mass, changes in local drainage conditions, and changes in exposure including reflected heat from adjacent hard surfaces. To mitigate these concerns the following guidelines should be followed:

- Soil moisture conditions within the tree root protection zones should be monitored during hot and dry weather. When soil moisture is inadequate, supplemental irrigation should be provided that penetrates soil to the depth of the root system or a minimum of 30 cm.
- Any planned changes to surface grades within the TPZs, including the placement of mulch, should be designed so that any water will flow away from tree trunks.
- Excavations adjacent to trees can alter local soil hydrology by draining water more rapidly from TPZs more rapidly than it would prior to site changes. It is recommended that when excavating within 6 m of any tree, the site be irrigated more frequently to account for this.

Root Zone Enhancements and Fertilization

Root zone enhancements such as mulch, and fertilizer treatments may be recommended by the project arborist during any phase of the project if they deem it necessary to maintain tree health and future survival.

Paving Within and Adjacent to TPZs

If development plans propose the construction of paved areas and/or retaining walls close to TPZs, measures should be taken to minimize impacts. Construction of these features would raise concerns for proper soil aeration, drainage, irrigation and the available soil volume for adequate root growth. The following design and construction guidelines for paving and retaining walls are recommended to minimize the long-term impacts of construction on protected trees:

- Any excavation activities near or within the TPZ should be monitored by a certified arborist. Structures should be designed, and excavation activities undertaken to remove and disturb as little of the rooting zone as possible. All roots greater than 2 cm in diameter should be hand pruned by a Certified Arborist.
- The natural grade of a TPZ should be maintained. Any retaining walls should be designed at heights that maintain the existing grade within 20 cm of its current level. If the grade is altered, it should be raised not reduced in height.
- Compaction of sub grade materials can cause trees to develop shallow rooting systems. This can contribute to long-term pavement damage as roots grow. Minimizing the compaction of subgrade materials by using structural soils or other engineered solutions and increasing the strength of the pavement reduces reliance on the sub-grade for strength.
- If it is not possible to minimize the compaction of sub-grade materials, subsurface barriers should be considered to help direct roots downward into the soil and prevent them from growing directly under the paved surfaces.

Plantings within TPZs

Any plans to landscape the ground within the TPZ should implement measures to minimize negative impacts on the above or below ground parts of a tree. Existing grass layer in TPZs should not be stripped because this will damage surface tree roots. Grass layer should be covered with mulch at the start of the project, which will gradually kill the grass while moderating soil moisture and temperatures. Topsoil should be mixed with the mulch prior to planting of shrubs, but new topsoil layer should not be greater than 20 cm deep on top of the original grade. Planting should take place within the newly placed topsoil mixture and should not disturb the original rooting zone of the trees. A two-meter radius around the base of each tree should be left unplanted and covered in mulch; a tree's root collar should remain free from any amendments that raise the surface grade.

Monitoring during construction

Ongoing monitoring by a consultant arborist should occur for the duration of a development project. Site visits should be more frequent during activities that are higher risk, including the first stages of construction when excavation occurs adjacent to the trees. Site visits will ensure contractors are

respecting the recommended tree protection measures and will allow the arborist to identify any new concerns that may arise.

During each site visit the following measures will be assessed and reported on by a consulting arborist:

- Health and condition of protected trees, including damage to branches, trunks and roots that may have resulted from construction activities, as will the health of. Recommendations for remediation will follow.
- Integrity of the TPZ and fencing.
- Changes to TPZ conditions including overall maintenance, parking on roots, and storing or dumping of materials within TPZ. If failures to maintain and respect the TPZ are observed, suggestions will be made to ensure tree protection measures are remediated and upheld.
- Review and confirmation of recommended tree maintenance including root pruning, irrigation, mulching and branch pruning.
- Changes to soil moisture levels and drainage patterns; and
- Factors that may be detrimentally impact the trees.

Appendix 7 Report Assumptions and Limiting Conditions

- 1) Unless expressly set out in this report or these Assumptions and Limiting Conditions, Diamond Head Consulting Ltd. (“Diamond Head”) makes no guarantee, representation or warranty (express or implied) regarding this report, its findings, conclusions or recommendations contained herein, or the work referred to herein.
- 2) The work undertaken in connection with this report and preparation of this report have been conducted by Diamond Head for the “Client” as stated in the report above. It is intended for the sole and exclusive use by the Client for the purpose(s) set out in this report. Any use of, reliance on or decisions made based on this report by any person other than the Client, or by the Client for any purpose other than the purpose(s) set out in this report, is the sole responsibility of, and at the sole risk of, such other person or the Client, as the case may be. Diamond Head accepts no liability or responsibility whatsoever for any losses, expenses, damages, fines, penalties or other harm (including without limitation financial or consequential effects on transactions or property values, and economic loss) that may be suffered or incurred by any person as a result of the use of or reliance on this report or the work referred to herein. The copying, distribution or publication of this report (except for the internal use of the Client) without the express written permission of Diamond Head (which consent may be withheld in Diamond Head’s sole discretion) is prohibited. Diamond Head retains ownership of this report and all documents related thereto both generally and as instruments of professional service.
- 3) The findings, conclusions and recommendations made in this report reflect Diamond Head’s best professional judgment given the information available at the time of preparation. This report has been prepared in a manner consistent with the level of care and skill normally exercised by arborists currently practicing under similar conditions in a similar geographic area and for specific application to the trees subject to this report on the date of this report. Except as expressly stated in this report, the findings, conclusions and recommendations it sets out are valid for the day on which the assessment leading to such findings, conclusions and recommendations was conducted. If generally accepted assessment techniques or prevailing professional standards and best practices change at a future date, modifications to the findings, conclusions, and recommendations in this report may be necessary. Diamond Head expressly excludes any duty to provide any such modification if generally accepted assessment techniques and prevailing professional standards and best practices change.
- 4) Conditions affecting the trees subject to this report (the “Conditions”, include without limitation, structural defects, scars, decay, fungal fruiting bodies, evidence of insect attack, discolored foliage, condition of root structures, the degree and direction of lean, the general condition of the tree(s) and the surrounding site, and the proximity of property and people) other than those expressly addressed in this report may exist. Unless otherwise stated information contained in this report covers only those Conditions and trees at the time of inspection. The inspection is limited to visual examination of such Conditions and trees without dissection, excavation, probing or coring. While

every effort has been made to ensure that any trees recommended for retention are both healthy and safe, no guarantees, representations or warranties are made (express or implied) that those trees will not be subject to structural failure or decline. The Client acknowledges that it is both professionally and practically impossible to predict with absolute certainty the behavior of any single tree, or groups of trees, in all given circumstances. Inevitably, a standing tree will always pose some risk. Most trees have the potential for failure and this risk can only be eliminated if the risk is removed. If Conditions change or if additional information becomes available at a future date, modifications to the findings, conclusions, and recommendations in this report may be necessary. Diamond Head expressly excludes any duty to provide any such modification of Conditions change or additional information becomes available.

- 5) Nothing in this report is intended to constitute or provide a legal opinion and Diamond Head expressly disclaims any responsibility for matters legal in nature (including, without limitation, matters relating to title and ownership of real or personal property and matters relating to cultural and heritage values). Diamond Head makes no guarantee, representation or warranty (express or implied) as to the requirements of or compliance with applicable laws, rules, regulations, or policies established by federal, provincial, local government or First Nations bodies (collectively, “Government Bodies”) or as to the availability of licenses, permits or authorizations of any Government Body. Revisions to any regulatory standards (including by-laws, policies, guidelines an any similar directions of a Government Bodies in effect from time to time) referred to in this report may be expected over time. As a result, modifications to the findings, conclusions and recommendations in this report may be necessary. Diamond Head expressly excludes any duty to provide any such modification if any such regulatory standard is revised.
- 6) Diamond Head shall not be required to give testimony or to attend court by reason of this report unless subsequent contractual arrangements are made, including payment of an additional fee for such services as described in the fee schedule and contract of engagement.
- 7) In preparing this report, Diamond Head has relied in good faith on information provided by certain persons, Government Bodies, government registries and agents and representatives of each of the foregoing, and Diamond Head assumes that such information is true, correct and accurate in all material respects. Diamond Head accepts no responsibility for any deficiency, misinterpretations or fraudulent acts of or information provided by such persons, bodies, registries, agents and representatives.
- 8) Sketches, diagrams, graphs, and photographs in this report, being intended as visual aids, are not necessarily to scale and should not be construed as engineering or architectural reports or surveys.
- 9) Loss or alteration of any part of this report invalidates the entire report.